

TOTAL NOOF ENGINEER STANDER

From appropriate actwork (ATRI; H; TDRI; WDRI) Service de-Multiplexing/

Segmentation (Packetization)

Add Header (Tag) 48

Switch to Trunk (according to Tag)

Insert Packets into OC-48c PoS frame

Switch OC-48c To optical Tx Sy (WDM-option)

Downstream

F(C, S

To appropriate network (A TIM; IP; TDIM; WIDM Service Multiplexing/Aggregation Reassembly of specific service


38 - Remove Header (Tag)

Switch from Trunk (according to Tag)

Remove Packets from OC-48c frame

Switch optical signal (WDM-option) to appropriate OC-48 framer

100



124 102 Optical Transciever (WDM - Optional) Optical Transciever (WDM - Optional) CPU OC-48c Stream Switch (Optional) 104 OC48c POS Framing OC48c POS Framing 108 S 5 1 RANS Packet Switch 3- - N----Y 111 Tagging Tagging Tagging Packetization (Segmentation/ Reassembly) Packetization (Segmentation/ Reassembly) Packetization (Segmentation/ Reassembly) 110 114 Service Service TDM Aggregation (2.2) Facing IP Aggregation ATM Aggregation المحتدة المحتدة ~